

Function Key / Key Stroke Mask

Graphing	Help	Open Graph	Clear Graphs	Remove Selected
	F1	F2	F3	F4
	Help	Step Test	Hold At	Sweep Linear
Ctrl +	Save Run	Open Graph	Manual Start/ Finish	FixedStart/ Finish
Shift +	Gear Ratio Input	Tacho Ratio Input		Clear Fixed Ratios

Graphing	Graph Properties	Area Properties	Area Annotations	A/F Properties
	F5	F6	F7	F8
	Sweep Squared	Fixed Load	Manual Load	
Ctrl +	Tacho Properties	Speed Properties	A/F Properties	Odometer

Graphing	A/F Annotations		Climate Warnings	Exit
	F9	F10	F11	F12
	Load-Cell Set-up		Auto-Deceleration	Cancel all Modes
Ctrl +	Climate Properties		R-D Calibration	Exit

Graphing	Help	Open Graph	Clear Graphs
	F1	F2	F3
	Help	Step Test	Hold At
Ctrl +	Save Run	Open Graph	Manual Start/ Finish
Shift +	Gear Ratio Input	Tacho Ratio Input	

Remove Selected	Graph Properties	Area Properties
F4	F5	F6
Sweep Linear	Sweep Squared	Fixed Load
FixedStart/ Finish	Tacho Properties	Speed Properties
Clear Fixed Ratios		

Area Annotations	A/F Properties	A/F Annotations
F7	F8	F9
Manual Load		Load-Cell Set-up
A/F Properties	Odometer	Climate Properties

	Climate Warnings	Exit
F10	F11	F12
	Auto-Deceleration	Cancel all Modes
	R-D Calibration	Exit

Print out these Function Key masks and place on keyboard above the Function Keys.